



**NELSON'S
LABELS**

NELSONS LABELS (MANCHESTER) LIMITED
UNIT 3 · WHARFSIDE COMMERCE PARK
WATERSIDE · MANCHESTER M17 1WD
TELEPHONE: +44 (0)161 873 4500
FAX: +44 (0)161 873 4505
ISDN: +44 (0)161 873 4501
E-mail: sales@nelsons-labels.co.uk
NELSONS LABELS (MANCHESTER) LIMITED

**NELSONS LABELS
(MANCHESTER) LTD.
FIRE TICKETS & LABELS
SUPPLIED FROM STOCK**

FOR BEDS



RESISTANT

Complies with
BS 7177 : 1996
for domestic use
(low hazard)



RESISTANT


Complies with
BS 7177 : 1996
for medium hazard



RESISTANT

Complies with
BS 7177 : 1996
for high hazard

FOR FURNITURE



RESISTANT

Filling material(s) and covering fabric(s) meet the requirements for resistance to cigarette and match ignition in the 1988 safety regulations

CARELESSNESS CAUSES FIRE

GRS/GRU

CARELESSNESS CAUSES FIRE

Batch/I.D. No.....

To comply with the Furniture and Furnishings (Fire) (Safety) Regulations 1988:

this item does contain a Schedule 3 interliner,

all foams, fillings and composites have been tested by our suppliers to ensure compliance with the relevant, ignitability test,

covers and fillings are cigarette resistant, covers are not match resistant.

Further details are available from your retailer.

CCFSOB

CARELESSNESS CAUSES FIRE

Batch/I.D. No.....

To comply with the Furniture and Furnishings (Fire) (Safety) Regulations 1988:

this item does contain a Schedule 3 interliner,

all foams, fillings and composites have been tested by our suppliers to ensure compliance with the relevant, ignitability test,

covers and fillings are cigarette resistant, covers are not match resistant.

Further details are available from your retailer.

CCFSAB

CARELESSNESS CAUSES FIRE

Batch/I.D. No.....

To comply with the Furniture and Furnishings (Fire) (Safety) Regulations 1988:

this item does not require a Schedule 3 interliner,

all foams, fillings and composites have been tested by our suppliers to ensure compliance with the relevant, ignitability test,

covers and fillings are cigarette resistant, covers are match resistant.

Further details are available from your retailer.

CCFSAG

CARELESSNESS CAUSES FIRE

Batch/I.D. No.....

To comply with the Furniture and Furnishings (Fire) (Safety) Regulations 1988:

this item does not require a Schedule 3 interliner,

all foams, fillings and composites have been tested by our suppliers to ensure compliance with the relevant, ignitability test,

covers and fillings are cigarette resistant, covers are match resistant.

Further details are available from your retailer.

CCFSOG


CTS/CTU



Meets the 1988 safety regulations by inclusion of a fire resistant interliner


CAUTION CARELESSNESS CAUSES FIRE

CPS/CPU



Careless use of matches could set fire to this product

CAUTION



RESISTANT

Complies with BS 7176 : 1995 direct test/predictive test²⁾ for low hazard (not recommended for use in higher hazard areas)

BS7176L

CARELESSNESS CAUSES FIRE

To comply with the Furniture and Furnishings (Fire)(Safety) Regulations 1988.

All fillings have been tested by our suppliers to ensure compliance with the relevant ignitability test.

CCFPC



RESISTANT

Complies with BS 7176 : 1995 direct test/predictive test²⁾ for medium hazard (not recommended for use in higher hazard areas)

BS7176M